

## Military Construction

*Recipient:* Fort Indiantown Gap

*Amount Requested:* \$1,980,000

*Recipient's Address:* 0-10 Fort Indiantown Gap  
Annville, PA 17003

*Project Description:* A paint stripping booth and paint preparation bay is required for the CSMS Vehicle Paint Shop to operate safely and efficiently. The CSMS supports 4,500 pieces of military vehicles, generators and trailers as well as small work order projects such as detailing, sign making and stenciling. CURRENT SITUATION: DEP Violation. Current wash operation is conducted outside of existing CSMS painting facility - drain is situated in a paved area in front of maintenance bays. Slope/drainage is such that it intakes a tremendous amount of storm water adding substantially to our Inflow and Infiltration (I&I) problem for our Waste Water Treatment Plant (WWTP). Result is periodic overflows and Notice of Violations from the Pennsylvania Department of Environment protection. We have an MOA with DEP to develop a plan (in progress) to fix our I&I problems over time. The CSMS drain is not the only reason for overflows, but a significant aspect. This is a known published finding by EPAS Environmental Performance Assessment System (EPAS) NGB-ARE environmental audit 2003, and a repeat finding in the August 2007 EPAS.

---